



C-10839 Crankshaft Assy. Complete (SAE No. 20 Spline).  
 Crankshaft similar to C-10369 except it has 2-1/2" Crankpins.  
 The larger crankpins increased the torsional stiffness by ~40%.  
 J Riend 22nov22

NOTE:  
 These drawings may be used solely for non-commercial use such as historical research,  
 exhibition, model-making, or for non-profit restoration purposes. Models or restored aircraft  
 must remain inoperable and incapable of flight. Drawings may not be used to restore operable  
 aircraft, or engines, to an airworthy status or building flyable or operable reproductions or restorations.